

Estimate for - Repairing of damaged floor and painting of front Part of Vivek Bhan at 68 KB Sarami under WBUT KOT-37.

Page NO	Qt NO	Description of Item	Quantity	Unit	Rate / Am
	1	Taking out carefully existing ceramic floor tiles and keeping them as directed	35.00	m ²	
P-11 Qt-5	2	cement concrete with graded 20mm down stone chips mix (1:2:4) in ground floor	1.50	m ³	
P-52 Qt-30	3	Supplying fitting & fixing 1st quality ceramic tiles in walls and floor to match with the existing work etc and finishing the joints with white cement mixed with colour pigment oxide if required to match the colour of tiles including roughening of the concrete surface all complete area above 0.09m ² floor other than colour decorative including white	36.00	m ²	
P-155 Qt-2	4	Scraping of moss, blisters etc thoroughly from exterior wall	250.00	m ²	
P-158 Qt-15	5	Applying Exterior grade Acrylic primer of approved quality and brand on plastered surface to receive decorative or smooth finish.	350.00	m ²	
P-159 Qt	6	Protective and decorative Acrylic exterior emulsion paints of approved quality as per manufacturers specification and as per direction of E.I.C. including cost of all materials & labour charge.	350.00	m ²	
P-151 Qt 1	7	Labour charge of chipping plaster and raking out joints	30.00	m ²	
P-151 Qt 2(i)	8	15mm thick plaster with cement mortar (1:4) - - -	38.00	m ²	
P-152	9	Painting one coat on plaster / timber surface - - -	40.00	m ²	
Qt-7 Qt-16 Qt-8	10	Painting with best quality synthetic oil bound paints of approved make high gloss	40.00	m ²	

Room

05/07/2017

SUB-ASSISTANT ENGINEER
West Bengal University of
Animal and Fishery Sciences

(Er. S. Roy)
B.C.E. M.B.A.

Consultant Engr